



Program Start February 2002

**1999-2000 Protege with 1.6L
Engine Mass Airflow Sensor Warranty Extension Program
(Non-California Emission Control Warranty Only)
[Special Service Program SSP56]**

TO: All **Mazda** Dealers

ATTENTION: All General Managers, Service Managers, and Parts Managers

SUBJECT: **Special Service Program-SSP56**
1999-2000 Protege with 1.6L Engine
(Non-California Emission Control Warranty Only)
Mass Airflow Sensor Warranty Extension Program

Dear **Mazda** Dealer:

Mazda Motor Corporation is extending the warranty coverage of the Mass Airflow Sensor on certain 1999- 2000 Protege vehicles with the 1.6L engine and Non-California Emission Control Warranty. The extended warranty is available for 7 years from the original warranty start date or 70,000 miles, which ever occurs first. ***This warranty extension program is provided in the interest of customer satisfaction.***

There is a possibility that a malfunction of the Mass Airflow Sensor may cause a Check Engine/MIL illumination and/or poor driveability. Symptoms may include a lack of power, hesitation, or unstable idle. **Failure of the Mass Airflow Sensor will not cause failure of other components.** Other components that can cause these symptoms are not covered under this extended warranty program.

Owners of subject vehicles will be notified by first class mail in three phases. **Owners will be advised they do not need to have their vehicle inspected if it is functioning normally.** Detailed information regarding this Warranty Extension Program is provided in Attachment I.

Please make certain that the appropriate personnel in your dealership are familiar with the details of this Warranty Extension Program for responding to customer inquiries. Should you have any questions, please contact the **Warranty Hotline at (800)-662-6779.**

NOTE: THIS IS NOT A RECALL; IT IS A WARRANTY EXTENSION FOR THE SPECIFIED PART ONLY. INSPECTION AND REPLACEMENT OF NON-FAILED PARTS WILL NOT BE ELIGIBLE FOR REIMBURSEMENT TO THE DEALER OR THE CUSTOMER. THIS PROGRAM EXTENDS THE WARRANTY PERIOD FOR ACTUAL FAILURES DUE TO DEFECTS IN WORKMANSHIP OR MATERIALS IN ACCORDANCE WITH MAZDA WARRANTY POLICY AND PROCEDURES.

Your understanding and support in carrying out this program is greatly appreciated.

Sincerely,

MAZDA NORTH AMERICAN OPERATIONS

WARRANTY EXTENSION

For certain 1999-2000 Protege vehicles with the 1.6L engine and Non-California Emission Control Warranty, the warranty coverage for the Mass Airflow Sensor is extended. **The extended warranty is available for 7 years from the original warranty start date or 70,000 miles**, which ever occurs first.

CONDITION OF CONCERN

There is a possibility that a malfunction of the Mass Airflow Sensor may cause a Check Engine/MIL illumination and/or poor driveability. Symptoms may include a lack of power, hesitation, or unstable idle.

SUBJECT VEHICLES

Model Year & Model	VIN Range	Build Date Range
1999-2000 Protégé 1.6L Engine (Non-California Emission Control Warranty)	JM1BJ22***0 100001 -JM1BJ22***0 300995	July 1, 1998- August 1, 2000

Note: The asterisk symbol "*" can be any letter or number.

OWNER NOTIFICATION

Owners of affected vehicles will be notified of the warranty extension program and advised **they do not need to come in for inspection if their vehicle is functioning normally**. Owners will be notified by first class mail in three phases, according to the following schedule:

Phase	Owner Notification Mail Date	Region
Phase 1	2-19-02	Northeast and Midwest
Phase 2	2-25-02	Southeast
Phase 3	3-4-02	Gulf and Western

PARTS INFORMATION

Part Description	Part Number	Quantity
Remanufactured Airflow Sensor	L321-13-215	1
Authorized Modification Label	9999-95-065A-00	1

NOTE: Part Number **ZL01-13-215R-00** is not longer available and has been superceded to part number **L321-13-215**.

Only defective Mass Airflow Sensors qualify for the warranty extension program.

Parts can be ordered from dealer's facing PDC as needed. They will not be pre-shipped to dealers.

NOTE: EXISTING (NEW) PART NUMBER ZL01-13-215 IS NOT APPLICABLE TO THIS PROGRAM AND CANNOT BE CLAIMED OR REIMBURSED FOR WARRANTY UNDER SSP56.

Authorized Modification Labels are supplied at no charge and are available in 8 1/2" x 11" sheets containing 18 labels. Please use Mstore to order additional labels.

REPAIR PROCEDURE

Refer to Protégé Workshop Manual.

WARRANTY INFORMATION

	Inspection & Replacement
Process Number	A0298H
Warranty Type Code	R
Symptom Code	99
Damage Code	99
Part Number Main Cause	L321-13-215
Quantity	1
Labor Operation Code / Labor Hours	
Air Flow Sensor R&R	XX351XRX / 0.5
Diagnostic Time (Max.)	XX402XRX / 0.5